


Beeman
Jones 1-11
Location ID: 316760



Location



Location

Beeman
Jones 1-11
Location ID: 316760



Location



Location

Beeman
Jones 1-11
Location ID: 316760



Well head signage



Load line missing cap/plug

Beeman
Jones 1-11
Location ID: 316760



Staining



Weeds in containment

Beeman
Jones 1-11
Location ID: 316760



Weeds in containment



2 tanks with proper labeling

Beeman
Jones 1-11
Location ID: 316760



2 tanks missing labeling



Staining and debris

Beeman
Jones 1-11
Location ID: 316760



Belt guard missing



Staining

Beeman
Jones 1-11
Location ID: 316760



Staining



Staining

Beeman
Jones 1-11
Location ID: 316760



Open hole for wildlife to enter



Debris

Beeman
Jones 1-11
Location ID: 316760



Tank labeling falling off



Open pit