

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Location



Location

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Stored equipment



Staining

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Debris



Debris

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Location



Location

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Thief hatches



Staining, unknown bucket

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Staining



Stored equipment

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Location



Unused equipment



Beeman
PEOC-NVG 41-23H
Location ID: 316766



Unused equipment



Location

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Staining



Staining

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Staining and unknown buckets



Staining

Beeman
PEOC-NVG 41-23H
Location ID: 316766



Staining down tank



Thief hatch leaking

Beeman
PEOC-NVG 41-23H
Location ID: 316766



ECD burning