

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 07/10/2024 Document Number: 403849757

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10690 Contact Person: Brent Bongers Company Name: IMPETRO RESOURCES LLC Phone: (361) 935-5633 Address: 558 CASTLE PINES PKWY UNIT B-4 Fax: () City: CASTLE PINES State: CO Zip: 80108 Email: bbongers@impetroresources.com

Identification Information

API Number: 05 - - ECMC Facility ID: 264817 Initial Form 19 or 27 Document number: Facility Name: CHRISTIANSON Facility Number: 21-12 Facility Type: PIT Location QtrQtr: NENW Section: 12 Township: 3S Range: 50W Meridian: 6 County: WASHINGTON Field Name: SPOTTED DOG Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS, Inc. Agent Name: Drezden Kinnaird Title: Project Manager Phone Number: 970-493-7780 Email: dkinnaird@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 02/22/2024 On inspection the Pit was: [X] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 771078 Facility Name: Christianson 909J Facility Facility Type: Oil/Gas Production Facility Location: QtrQtr: NENW Sec: 12 Twp: 3S Range: 50W Meridian: 6 County Name: WASHINGTON Latitude: 39.814169 Longitude: -102.925805

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 120529 Document Name: EDD File Name: 2402403-01RF2 - Impetro 909J 2024 - Christianson (spotted dog).xlsx Sample Type: Matrix: Facility ID: 771078 Sample ID: 660146 Sample Name: Christianson (Spotted Dog) Sample Date: 02/22/2024 Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Lab Sample ID: L1709480-01

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
771078	403849763	2402403-01RF2 - Impetro 909J 2024 - Christianson (spotted dog).pdf	Analytical Laboratory Report	PDF

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
660146	121-10634	CHRISTIANSON 32-12	Rule 909.j subsequent sample
660146	121-10654	CHRISTIANSON 21-12	Rule 909.j subsequent sample
660146	121-10680	CHRISTIANSON 21A - 12	Rule 909.j subsequent sample
660146	121-10681	CHRISTIANSON 21B-12	Rule 909.j subsequent sample
660146	121-10687	CHRISTIANSON 22-12	Rule 909.j subsequent sample
660146	121-10690	CHRISTIANSON-SWD 12-12	Rule 909.j subsequent sample

General Comments

User Group	Comment	Comment Date
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system. The EDD did not include analytical data for radium 226, 228, or 226+228.	07/31/2024
Total: 1 comment(s)		