

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403827778

Date Received:
06/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

CAERUS

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713400122

Inspection Date: 06/10/2024

FIR Submit Date: 06/12/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335510

Location Name: 697-28C-66S97W Number: 28NESW County: _____

Qtrqtr: NESW Sec: 28 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.491380 Longitude: -108.229360

FACILITY - API Number: 05-045-00 Facility ID: 335510

Facility Name: 697-28C-66S97W Number: 28NESW

Qtrqtr: NESW Sec: 28 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.491380 Longitude: -108.229360

CORRECTIVE ACTIONS:

1 CA# 195834

Corrective Action: All load lines or tank valves that can be used as a load line will be capped or plugged.

Date: 06/19/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator Comment: Installed bull pugs on all open ended valves

ECMC Decision: _____

Date: 06/19/2024

Date of Completion: 06/17/2024

Closed doors on separator

--

Signed:

Date: 6/18/2024 7:22:54 AM

<u>Document Number</u>	<u>Description</u>
403827778	FIR RESOLUTION SUBMITTED
403827790	Installed bull plugs
403827794	Closed doors

Page 2 of 2