

## Inspection Photos


Location Name: CAERUS PICEANCE LLC, BENTLEY-67S95W/11SENE

Location ID: 324025

Date: 7/31/2024



Location Entrance – Photo #02496



Wellhead – Photo #02497



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, BENTLEY-67S95W/11SENE

Location ID: 324025

Date: 7/31/2024



Separator – Photo #02502



Tank Battery – Photo #02498





## Inspection Photos

Location Name: CAERUS PICEANCE LLC, BENTLEY-67S95W/11SENE

Location ID: 324025

Date: 7/31/2024



**No Berm Liner Installed – Photo #02500**



**No Berm Liner Installed – Photo #02501**