

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, MAP LLC-67S95W/11NESW

Location ID: 334733

Date: 7/31/2024



North End of Location – Photo #02519



Wellheads – Photo #02517

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, MAP LLC-67S95W/11NESW

Location ID: 334733

Date: 7/31/2024



Jul 31, 2024 at 12:41:17  
Parachute CO 81635  
United States

Separators – Photo #02515



Jul 31, 2024 at 12:40:16  
Parachute CO 81635  
United States

Tank Battery – Photo #02513



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, MAP LLC-67S95W/11NESW

Location ID: 334733

Date: 7/31/2024



Gas Meter – Photo #02514



Lack of Stabilization – Photo #02516

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, MAP LLC-67S95W/11NESW

Location ID: 334733

Date: 7/31/2024



**Unprotected Soil Stockpile – Photo #02518**