

Inspection Photos

07/31/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 324001

Inspection Doc: 696206078

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 324001



Photo 1: Photos taken from the Location entrance, on the southwest end of the Location. Photos provide an overview of the Location facing northeast and east. Photo also shows fence at entrance is in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 324001



Photo 2: Photos 2-3 taken from the southwest end of the Location. Photos provide an overview from southwest, west, north to northeast. production and surface equipment have been removed from the Location; no other reclamation work including, but not limited, removal of gravel, compaction alleviation, recontouring/regrading, replacement of topsoil and revegetation activities have been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 324001



Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 324001



Photo 4: Photo example showing gravel remaining, and Undesirable Plant establishment (Kochia, Russian thistle) throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources