

Inspection Photos

07/31/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 323905

Inspection Doc: 696206082

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323905



Photo 1: Photos 1-2 taken from the northeast end of the Location, facing southwest and west. The former working pad surface has met ECMC 1004.c revegetation standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323905



Photo 2: Photos 2-4 examples showing reclamation work including, but not limited to, removal of gravel, compaction alleviation, contouring and reclamation work has not been performed at the access road in accordance with Rule 1004.a



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323905



Photo 3: See comments under photo 2.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323905



Photo 4: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323905



Photo 5: Photo example showing gravel/road base material remaining.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323905



Photo 6: Photo left 2016 Google Earth aerial imagery; Photo right 1993 Google Earth aerial imagery. Records show well was SPUD 7/13/1995. Photos show that the O&G access road (red line) did not pre-exist the O&G Location, and is subject to 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources