



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/24/2024

Photo #1 Tankbattery.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/24/2024

Photo #2 area of spill
#486930, below the
surface, the soil was
observed as moist with
hydrocarbon staining.

Jul 24, 2024 12:52:35 PM



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jul 24, 2024 12:52:36 PM

Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/24/2024

Photo #3 area of spill
#486930, below the
surface, the soil was
observed as moist with
hydrocarbon staining.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Iles Tank
Battery

Location ID:480890

Inspection Date: 7/24/2024

Photo #4 soil observed
from the spill area in spill
486930, observed
hydrocarbon staining.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Iles Tank

Battery

Location ID:480890

Inspection Date: 7/24/2024

Photo #5 REM 34712
cement sump structure.
Hydrocarbon odor noted.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Iles Tank

Battery

Location ID:480890

Inspection Date: 7/24/2024

Photo #6 REM 34712
cement sump structure.
Hydrocarbon odor noted.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Iles Tank
Battery
Location ID:480890
Inspection Date: 7/24/2024

Photo #7 gap below
perimeter fencing around
the cement sump. The
center of the photo shows
the reflection of light in
fluid.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources