

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DIAMOND ELK-67S95W/12NWNW

Location ID: 334712

Date: 7/31/2024



Location Entrance – Photo #02558



Wellheads – Photo #02562

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DIAMOND ELK-67S95W/12NWNW

Location ID: 334712

Date: 7/31/2024



Separators – Photo #02560



Tank Battery – Photo #02564

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DIAMOND ELK-67S95W/12NWNW

Location ID: 334712

Date: 7/31/2024



Fresh Water Tank – Photo #02561



Stored Equipment – Photo #02568

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DIAMOND ELK-67S95W/12NWNW

Location ID: 334712

Date: 7/31/2024



Damaged Battery Fencing – Photo #02565