

Operator: CPR

Location Name: SELTZER-61N67W 34SWSW

Loc ID: 333142

Inspection: 713900707



Exhibit A



Exhibit B

CA: This location does not comply with Rule 1004. Operator conducted reclamation activities according to FIR #697503897 however the access road and well location are dominated by thistle and Downy Brome List B and C CO Noxious weeds and don't appear to be being managed. No disturbance /Location never built. Comply with Rule 1004. Manage noxious weeds along the access road and well location.

CA Resolution: Operator has reported that this location has been mowed with a bagging attachment to collect developed seed heads from cheat grass and other weeds on location. Operator has also noted that seeding is planned for the late summer/ fall when temps drop, and moisture is more consistent.