

# Inspection Photos

Loc: 428957

Operator: **WINN EXPLORATION CO INC**

Inspection Date: 8/5/2024

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the location.





## Inspection Photos



**Photo 2.** Southeast corner of the location facing northwest. Red arrow points to degraded wattles that have not been removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:428957 | Date: 8/5/2024



## Inspection Photos



**Photo 3.** Southwest corner of the location facing north. Red arrow points to degraded wattles that have not been removed.





## Inspection Photos



**Photo 4.** There is a pile of gravel stored on the location.

