

**Hilcorp Energy Company  
Hiawatha B-2  
Location ID: 313074**



**Debris**



**Fading and peeling labels**



Hilcorp Energy Company  
Hiawatha B-2  
Location ID: 313074




**No labels. Unused equipment. Open to wildlife.**



**No labels. Unused equipment. Open to wildlife.**

**Hilcorp Energy Company**  
**Hiawatha B-2**  
**Location ID: 313074**




**Staining**



**Cap drip. Valve open inside pot.**



Hilcorp Energy Company  
Hiawatha B-2  
Location ID: 313074



**Leak. Stained soil.**



**Missing required information**

Hilcorp Energy Company  
Hiawatha B-2  
Location ID: 313074



Missing required information



Debris



Hilcorp Energy Company  
Hiawatha B-2  
Location ID: 313074



Missing required information



Chunks of oily waste



**Hilcorp Energy Company**  
**Hiawatha B-2**  
**Location ID: 313074**



**Chunks of oily waste**



**Chunks of oily waste**



**Hilcorp Energy Company**  
**Hiawatha B-2**  
**Location ID: 313074**



**Chunks of oily waste**



**Chunks of oily waste**



**Hilcorp Energy Company**  
**Hiawatha B-2**  
**Location ID: 313074**




**Weeds**



**Weeds**



Hilcorp Energy Company  
Hiawatha B-2  
Location ID: 313074



When replaced additional information is required



When replaced additional information is required



**Hilcorp Energy Company  
Hiawatha B-2  
Location ID: 313074**



**Location from Southeast corner**



**Location from Southwest corner**



**Hilcorp Energy Company  
Hiawatha B-2  
Location ID: 313074**



**Location from Northwest corner**



**Location from Northeast corner**