

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692



Photo # 4867 From entrance to location




Photo # 4868 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692

Aug 6, 2024 at 10:08:52 AM



Photo # 4869 Location

Aug 6, 2024 at 10:14:56 AM
CO



Photo # 4870 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692



Photo # 4871 Location



Photo # 4872 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692



Photo # 4873 Location



Photo # 4874 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692



Photo # 4875 Location



Photo # 4876 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692



Photo # 4877 Location



Photo # 4878 Netting/wildlife protection on containment needs maintenance/containment open to entry by wildlife /wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692



Photo # 4879 Netting/wildlife protection on containment needs maintenance/netting is sagging & partially submerged in unknown fluid/wildlife hazard



Photo # 4880 Netting/wildlife protection on containment needs maintenance/netting is sagging & partially submerged in unknown fluid/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692



Photo # 4881 Unmarked deadman



Photo # 4882 Same unmarked deadman from another angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad

Location ID: 159692



Photo # 4883 Improperly marked deadman