

Inspection Photos

08/06/2024

Operator: ENCANA OIL & GAS (USA) INC -
100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443

Inspection Doc: 696206092

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENCANA OIL & GAS (USA) INC - 100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443



Photo 1: Photos 1-2 taken from the location entrance on the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENCANA OIL & GAS (USA) INC - 100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENCANA OIL & GAS (USA) INC - 100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443



Photo 3: Photo taken from the southwest end of the Location, facing south. Photo shows tank battery facility. Signage indicates facility belongs to Caerus; signage on methanol tank in photo right shows ownership to be Encana.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENCANA OIL & GAS (USA) INC - 100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443



Photo 4: Photos taken from the northwest end of the Location. Photo shows signage at tank is no longer legible. Photo also shows wildlife protection BMPs at the secondary containment BMP are missing or insufficient.

Inspection Photos

Operator Name: ENCANA OIL & GAS (USA) INC - 100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443



Photo 5: Continued from photo 4. Photo shows various trash and debris improperly stored within the containment measure.

Inspection Photos

Operator Name: ENCANA OIL & GAS (USA) INC - 100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443



Photo 6: Photo taken from the northwest end of the Location. Photo shows contents labeling is no longer legible.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENCANA OIL & GAS (USA) INC - 100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443



Photo 7: Photos examples showing weed establishment observed throughout the working pad surface, and around equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ENCANA OIL & GAS (USA) INC - 100185 / CAERUS PICEANCE LLC - 10456

Location ID: 423443



Photo 8: Photo taken from the Location entrance. Photo shows culvert has been crushed and is in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources