

Inspection Photos


Location: TEP Rocky Mountain LLC Bosely/GM 34-14

Location ID: 334753

Date: 7/31/2024



Entrance to location - Photo #03848



Location - Photo #03859

Inspection Photos

Location: TEP Rocky Mountain LLC Bosely/GM 34-14

Location ID: 334753

Date: 7/31/2024



Wellheads - Photo #03850



Separators - Photo #0353

Inspection Photos

Location: TEP Rocky Mountain LLC Bosely/GM 34-14

Location ID: 334753

Date: 7/31/2024



Wildlife hazard - Photo #03855



Tank battery - Photo #03858

Inspection Photos

Location: TEP Rocky Mountain LLC Bosely/GM 34-14

Location ID: 334753

Date: 7/31/2024



Open ended load line - Photo #03868



Northeast corner of location - Photo #03873

Inspection Photos

Location: TEP Rocky Mountain LLC Bosely/GM 34-14

Location ID: 334753

Date: 7/31/2024



Northwest corner of location - Photo #03874

