

**Inspection Photos**  
**Location Name: Waves 1H**  
**Location ID: 430662**



**Photo 1 – Wellhead**

**Photo 2 – Gas Engine**

Inspection Photos  
Location Name: Waves 1H  
Location ID: 430662



Energy and Carbon Management Commission  
40-55411, -104-06889, 4847-311  
07/24/2024 13:51:17

Photo 3 – Well Sign



Energy and Carbon Management Commission  
40-55367, -104-06941, 4847-411  
07/24/2024 13:53:58

Photo 4 – Flare and ECD

**Inspection Photos**  
**Location Name: Waves 1H**  
**Location ID: 430662**



**Photo 5 – Valves to Flare appear to be in Open position**



**Photo 6 – Pilot Supply Valve appears to be in Closed position**

**Inspection Photos**  
**Location Name: Waves 1H**  
**Location ID: 430662**



Energy and Carbon Management Commission  
40.55365, -104.0694, 4849.8ft  
07/24/2024 13:54:26



Energy and Carbon Management Commission  
40.55363, -104.06941, 4846.4ft  
07/24/2024 13:55:04

**Photo 7 – Today Total at Flare Gas Meter**

**Photo 8 – Flow Rate**

**Inspection Photos**  
**Location Name: Waves 1H**  
**Location ID: 430662**



Energy and Carbon Management Commission  
40.55363, -104.06941, 4846.4ft  
07/24/2024 13:55:15



Energy and Carbon Management Commission  
40.55384, -104.06957, 4845.5ft  
07/24/2024 13:55:42

**Photo 9 – Yesterday Total**

**Photo 10 – Heater Treater**

**Inspection Photos**  
**Location Name: Waves 1H**  
**Location ID: 430662**



Energy and Carbon Management Commission  
40.55401, -104.06959, 4849.2ft  
07/24/2024 13:55:54




Energy and Carbon Management Commission  
40.55401, -104.06959, 4849.1ft  
07/24/2024 13:55:58

**Photo 11 – Sales Line**

**Photo 12 – Sales Line**

**Inspection Photos**  
**Location Name: Logan 2H**  
**Location ID: 430811**




**Photo 13 – Sales Line Valve appears to be in the closed position**



**Photo 14 – Sales Line**

**Inspection Photos**  
**Location Name: Waves 1H**  
**Location ID: 430662**



Energy and Carbon Management Commission  
40.55404, -104.06975, 4848.8ft  
07/24/2024 13:56:46



**Photo 15 – Sales Line Valve appears to be in Closed position**



Energy and Carbon Management Commission  
40.55404, -104.06974, 4850.6ft  
07/24/2024 13:56:56

**Photo 16 – Gas Sales Meter appears to be powered off**

**Inspection Photos**  
**Location Name: Waves 1H**  
**Location ID: 430662**



**Photo 17 – Gas Meter Calibration Card**

**Photo 18 – Gas Meter Calibration Card**

Inspection Photos  
Location Name: Waves 1H  
Location ID: 430662



**Photo 19 – Gas Meter valves appear to be in closed position**

**Photo 20 – Gas Sales Meter**

**Inspection Photos**  
**Location Name: Waves 1H**  
**Location ID: 430662**



**Photo 21 – Tank Battery**



**Photo 22 –Tank Battery Sign**