

# Inspection Photos

08/09/2024

**Operator:** VISION ENERGY LLC - 10770

**Location ID:** 322451

**Inspection Doc:** 696206104

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322451



**Photo 1:** Photos taken from the north end of the Location. Photos provide an overview of the Location from southeast to southwest. Unable to find evidence that reclamation and weed management activities have been performed. Various equipment/trash/debris/etc... remains stored on the southwest end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322451



**Photo 2:** Photos examples showing Location is not progressing towards 1004 standards. Vegetation observed is predominantly Undesirable Plant Species. Additional reclamation and weed management efforts have not been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources





August 9, 2024



August 9, 2024

**Photo 3:** Photo example of noxious weeds that have continued to establish and spread on the Location. Weeds include Musk Thistle, Common Mullein, Houndstongue, etc...



August 9, 2024



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources