

Peakview
Grassy creek coal #3
Location ID: 316759



Location



Location

Peakview
Grassy creek coal #3
Location ID: 316759



Debris



Well head

Peakview
Grassy creek coal #3
Location ID: 316759



Fill slope stabilized



Area of fill slope shows signs of erosion and lack of stabilization

Peakview
Grassy creek coal #3
Location ID: 316759



Area of fill slope shows signs of erosion and lack of stabilization



Debris

Peakview
Grassy creek coal #3
Location ID: 316759



Well head



Propane tanks not hooked up (unused equipment) also need proper labeling NFPA

Peakview
Grassy creek coal #3
Location ID: 316759



Propane tanks not hooked up (unused equipment) also need proper labeling NFPA



Unknown riser

Peakview
Grassy creek coal #3
Location ID: 316759



Open lines for wildlife to enter



Open lines for wildlife to enter

Peakview
Grassy creek coal #3
Location ID: 316759



Staining under load out bucket