

Inspection Photos

August 12th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333113

Inspection Document #: 714001068

La Plata County, CO

Township: SENE 12 32N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Margaret Montgomery A 1
Location ID: 333113

8/12/24
+37.034162,-107.879563
141° SE



Photo 1. View of the location taken from the access point facing center.

Inspection Photos

Location Name: Margaret Montgomery A 1

Location ID: 333113




Photo 2. View of weedy Kochia and Russian thistle observed throughout the location. This is considered debris and needs to be removed.

Inspection Photos
Location Name: Margaret Montgomery A 1
Location ID: 333113



Photo 3. Unlabeled tank on location.



Inspection Photos

Location Name: Margaret Montgomery A 1

Location ID: 333113



8/12/24

+37.033919,-107.880736

242° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised Western wheatgrass, Sand dropseed and Prairie sunflower.

API #: 067-07521