

Operator: Civitas N.


Location Name: HUNGENBERG-611N61W 29SWNW

Loc ID: 410182

Inspection: 691400020



North Oil & Gas
SHABLE 29-23
SWNW SEC.29-T11N-R61W
LAT. 40.89469 N LAT. 104.23706 W
720.370.5540 66-7762



CA: Stained soil around wellhead. Comply with Rule 603.f.

CA Resolution: Operator has provided photo evidence showing that the stained soil at the wellhead has been addressed in compliance with the 600 series.