

Operator: 8 NORTH LLC

Location Name: KAUFMAN PC GL20-68HN

Loc ID: 429749

Inspection: 696301573





CA: Stained Soil at Compressor drain vault, see photos. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

CA Resolution: Operator has provided photo evidence showing that the stained soil at the wellhead has been addressed in compliance with the 900 and 600 series.