

Operator: 8 North

Location Name: WELD-611N61W 28NESW

Loc ID: 310706

Inspection: 696301300



Exhibit A

CA: Wellhead Sign is missing. Comply with 210.b.

CA Resolution: Operator has provided photo evidence that a wellhead sign has been installed in compliance with Rule 210.b



Exhibit A



Exhibit B

CA: Unused Wellhead parts- Comply with Rule 603.f.

CA Resolution: Operator has provided photo evidence that unused wellhead parts have been properly removed or secured in compliance with the 600 series.