

Inspection Photos

08/09/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321

Inspection Doc: 696206126

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



Photo 1: Photos taken from the east end of the well Location. Photos provide an overview of the working pad from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



August 9, 2024



August 9, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



Photo 3: Photos taken from the interim areas of the Location. Location is not progressing towards 1003 reclamation standards; perennial establishment is not uniform and location is predominantly bare. Green vegetation observed is predominantly alfalfa and not reflective of the species within the adjacent reference areas



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



Photo 5: Photos taken from interim areas and slopes the the Battery Facility Location. Areas are predominantly bare and exposed soils; slopes lacks stabilization.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321



Photo 6: Photos examples of the adjacent reference areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383321




Photo 7: Photos show unused equipment, identified within previous inspections, remains stored on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources