

Interim Reclamation and Stormwater Inspection

Date: 08/13/2024

Operator: CRESTONE PEAK RESOURCES OPERATING
LLC - 10633

Location ID: 428697

Inspection Document #: 708201513

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Chavez 61N65W HZ Pad

Location ID: 428697



Photo 1. Erosion degradation observed on the southern production areas with sediment discharge into the interim areas. Also pictured, undesirable vegetation (kochia and russian thistle) observed to be growing. Pictured in background, the southern interim areas do not appear to be progressing towards reclamation standards and regulations with little evidence of desirable perennial vegetation observed.

Inspection Photos
Location Name: Chavez 61N65W HZ Pad
Location ID: 428697



Photo 2. Continued from Photo 2, facing east.

Inspection Photos

Location Name: Chavez 61N65W HZ Pad

Location ID: 428697



Photo 3. Undesirable vegetation observed throughout the production areas. Evidence of road base material/cobble observed in the eastern interim areas, illustrated by red arrow.

Inspection Photos

Location Name: Chavez 61N65W HZ Pad

Location ID: 428697




Photo 4. Continued from Photo 3; facing west.

Inspection Photos

Location Name: Chavez 61N65W HZ Pad

Location ID: 428697



Photos 5 & 6. Debris observed around wells should be removed from the location

Inspection Photos
Location Name: Chavez 61N65W HZ Pad
Location ID: 428697



Photo 7. Erosion degradation observed on the northern production areas with sediment discharge into the interim areas. Also pictured, undesirable vegetation (kochia and russian thistle) observed to be growing.

Inspection Photos
Location Name: Chavez 61N65W HZ Pad
Location ID: 428697



Photo 8. Continued from Photo 7; facing east. Pictured in background, the northern interim areas appear to be converted into cropland with poor crop growth observed, indicated by green arrow.

Inspection Photos
Location Name: Chavez 61N65W HZ Pad
Location ID: 428697



Photo 9. Undesirable vegetation growing throughout the access road.