

# Inspection Photos

08/16/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 311663

**Inspection Doc:** 696206138

Garfield County, CO

Aaron Trujillo  
Reclamation Work Lead  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



**Photo 1:** Photos 1-3 taken from the access road. Photos show BMPs, including a properly engineered stream crossing, has not been installed or maintained at the access road; degradation has persisted at the stream crossing.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



August 16, 2024



August 16, 2024

**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



**Photo 3:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources