

Inspection Photos

08/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742

Inspection Doc: 696206140

Garfield County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview from north, northeast, southeast to south. Photos also shows areas on the south end of the well pad not reasonably needed for production have not been reclaimed in accordance with 1003 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 3: Photos taken from the south end of the well pad, facing northwest and north. Photos show areas on the south end of the well pad are not reasonably needed for production, and have not been reclaimed in accordance with 1003 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 4: Google Earth aerial image. Red polygon represent approximate areas of the well pad not reasonable necessary for production activities.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 5: Photo shows unused pipe, trash and debris remain stored on the east end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 6: Unused equipment stored within containment at the battery facility.