

Inspection Photos

08/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788

Inspection Doc: 696206142

Garfield County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 1: BMPs to stabilize, as well as to minimize erosion and degradation remain missing or insufficient at the slopes on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 2: BMPs to stabilize, as well as to minimize erosion and degradation remain missing or insufficient at the slopes on Location. Lighter soils at toe of slopes sediment deposition due to unstablized slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources