

Inspection Photos

08/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777

Inspection Doc: 696206144

Garfield County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



Photo 1: An armored outlet has been implemented on the east end of the Location. Controls to properly divert stormwater to the outlet do not appear to have been implemented in conjunction with the outlet. Stormwater scouring/degradation is becoming evident at sides of the BMP.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



Photo 2: Marker at anchor has not been maintained and/or does not comport with 603.j requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources