

Interim Reclamation and Stormwater Inspection

Date: 8/14/24

Operator: PCR Operating LLC - 10657

Location ID: 454195

Inspection Document #: 713900877

Morgan County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: ADENA SOUTH WATER PLANT

Location ID: 454195



Photo 1. The photo was taken at the tank battery location facing South. The photo illustrates Kochia growing around the tank loadout, along the secondary containment berm and the location sign.

Photo 2. The photo was taken at the tank battery location facing South. The photo illustrates Kochia growing around the entire location and within secondary containment.

Inspection Photos

Location Name: ADENA SOUTH WATER PLANT

Location ID: 454195




Photo 3. The photo was taken at the tank battery location facing Southwest. Refer to the comment for photo 2.

Photo 4. The photo was taken at the tank battery location facing Southeast. The photo illustrates shotgun shells remain on the location noted in previous FIR.

Inspection Photos

Location Name: ADENA SOUTH WATER PLANT

Location ID: 454195




Photo 5. The photo was taken at the tank battery location facing South. The photo illustrates dribs and drabs from an unplugged loadout line.

Photo 6. The photo was taken at the tank battery location facing Southwest. The photo illustrates a shipping container on location that should have been removed per previous FIR as well as other unused equipment being stored on location.

Inspection Photos

Location Name: ADENA SOUTH WATER PLANT

Location ID: 454195



Photo 7. The photo was taken at the tank battery location facing West. The photo illustrates Kochia growing unmanaged around equipment.

Photo 8. The photo was taken at the tank battery location facing South. The photo illustrates unused equipment being stored on location.

Inspection Photos

Location Name: ADENA SOUTH WATER PLANT

Location ID: 454195



Photo 9. The photo was taken at the tank battery location facing Northeast. The photo illustrates Kochia growing unmanaged around equipment.

Photo 10. The photo was taken at the tank battery location facing Southeast. The photo illustrates unused equipment being stored on location.

Inspection Photos

Location Name: ADENA SOUTH WATER PLANT

Location ID: 454195



Photo 11. The photo was taken at the tank battery location facing South. The photo illustrates Kochia growing unmanaged around equipment.

Photo 12. The photo was taken at the tank battery location facing Northeast. The photo illustrates Kochia growing unmanaged around equipment.