

Operator: 8 North

Location Name: TROSTEL-611N61W 32SESW

Loc ID: 410140

Inspection: 684904655



Exhibit A



Exhibit B

CA: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence showing that the stained soil at the wellhead has been removed or remediated in compliance with the 600 series.



Exhibit A



Exhibit B



Exhibit C

CA: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence showing that the stained soil in engine house, and at exhaust has been removed or remediated in compliance with the 600 series.