

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403899329

Date Received:  
08/23/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:  
2 of 2 CAs from the FIR responded to on this Form  
2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10575  
Name of Operator: 8 NORTH LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
Luke Kelly 970-939-6353 lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 684905209  
Inspection Date: 04/03/2018 FIR Submit Date: 04/03/2018 FIR Status:

Inspected Operator Information:

Company Name: 8 NORTH LLC Company Number: 10575  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 306452

Location Name: FABRIZIUS-611N61W Number: 28NWNW County: WELD  
Qtrqtr: NWN Sec: 28 Twp: 11N Range: 61W Meridian: 6  
W  
Latitude: 40.898050 Longitude: -104.217900

FACILITY - API Number: 05-123-00 Facility ID: 288939

Facility Name: FABRIZIUS Number: 4-28  
Qtrqtr: NWN Sec: 28 Twp: 11N Range: 61W Meridian: 6  
W  
Latitude: 40.898050 Longitude: -104.217900

CORRECTIVE ACTIONS:

1 CA# 115509

Corrective Action: Comply with rule 603.f. Date: 05/03/2018

Response: CA COMPLETED Date of Completion: 07/23/2024

Operator Comment: Operator has addressed debris on location to comply with the 600 series.

ECMC Decision:

ECMC  
Representative:

**2** CA# 115510

Corrective Action: Comply with rule 603.f.

Date: 05/03/2018

Response: CA COMPLETED

Date of Completion: 07/23/2024

Operator Comment: Operator has provided photo evidence showing that the stained soil at the wellhead has been addressed in compliance with the 900 and 600 series.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 8/23/2024 12:41:46 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403899347	Inspection Report Resolution

Total Attach: 1 Files