

# Inspection Photos

08/21/2024

**Operator:** SWN PRODUCTION COMPANY LLC  
#10396

**Location ID:** 335174

**Inspection Doc:** 696206152

Moffat County, CO

Aaron Trujillo  
Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 335174



August 21, 2024



August 21, 2024

**Photo 1:** Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Location has not been reclaimed in accordance with 1004 requirements. Photo right also shows production equipment remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 335174



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 335174



**Photo 3:** Photo taken from the northwest end of the Location, facing southwest. Photo shows weeds (Scotch thistle), bare/unvegetated areas and a riser remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 335174



**Photo 4:** Photo taken from the north end of the Location. Photo shows signage/debris remaining.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 335174



**Photo 5:** Photo taken from the southern area of the Location, facing west and north. Location has not been reclaimed in accordance with 1004 Requirements. Areas where production equipment have been removed are not progressing towards 1004 uniform perennial vegetative establishment requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 335174



**Photo 6:** Photo taken from the area of the well. Gravel remains. Vegetative establishment is not uniform. Subsidence issues also observed at well site.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 335174



**Photo 7:** Photo taken from the southern area of the Location. Photos examples showing Knapweed (Green vegetation sans yellow flowers) establishment on the Location. Noxious weed establishment observed throughout the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 335174



August 21, 2024



August 21, 2024

**Photo 8:** Photos taken from the northern and southern areas of the Location. Photos examples showing Scotch thistle establishment on the Location. Noxious weed establishment observed throughout the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources