

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC
#10396

Location ID: 313132

Inspection Doc: 696206156

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313132



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos show access road has not been reclaimed in accordance with 1004 Requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313132



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313132



August 21, 2024

Photo 3: Photo taken from the southwest end of the Location, facing east. Photo shows access road has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313132



Photo 4: Photos examples showing Noxious weed (Scotch thistle) establishment observed throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources