

# Inspection Photos

08/21/2024

**Operator:** SWN PRODUCTION COMPANY LLC  
#10396

**Location ID:** 313147

**Inspection Doc:** 696206158

Moffat County, CO

Aaron Trujillo  
Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313147



**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos show access road has not been reclaimed in accordance with 1004 Requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313147



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313147



**Photo 3:** Photo show signage remaining. Utility equipment on and leading to location has not been removed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313147



**Photo 4:** Photo shows access road leading to location has not been reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313147



**Photo 5:** Photo left 2023 Google Earth aerial imagery. Photo right 1993 Aerial imagery. Photo shows Access road did not pre-exist the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources