

# Interim Reclamation and Stormwater Inspection

Date: 8/21/24

Operator: Crestone Peak Resources Operating LLC -  
10633

Location ID: 443722

Inspection Document #: 713900897

Arapahoe County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

# Inspection Photos

Location Name: Prosper Farms/4-65 2-1-6

Location ID: 443722



**Photo 1.** The photo was taken at the entrance to the well location facing East. The photo illustrates the entrance to the location and Operator signs.



**Photo 2.** The photo was taken at the well location facing North. The photo illustrates the northeastern sediment trap with ditch inlets and overflow outlet.

## Inspection Photos

Location Name: Prosper Farms/4-65 2-1-6

Location ID: 443722



**Photo 3.** The photo was taken at the well location facing Northwest. The photo illustrates puncturvine growing on the production pad.



**Photo 4.** The photo was taken at the well location facing West. The photo illustrates the ditch and berm around the exterior of the production pad and perimeter fence.

Note - Interim areas appear to have been mulch crimped and seeded.

## Inspection Photos

Location Name: Prosper Farms/4-65 2-1-6

Location ID: 443722



**Photo 5.** The photo was taken at the well location facing East. The photo illustrates filtrex wattle surrounding the topsoil stockpile. The area has also been seeded and crimped but at the moment is bare soil, kochia and russian thistle.

**Photo 6.** The photo was taken at the well location facing South. The photo illustrates the topsoil stockpile has been seeded and crimped and has a filtrex wattle surrounding the base.

## Inspection Photos

Location Name: Prosper Farms/4-65 2-1-6

Location ID: 443722



**Photo 7.** The photo was taken at the well location facing West. The photo illustrates a representative secondary containment of a tank is being maintained with wildlife protections.

**Photo 8.** The photo was taken at the well location facing South. The photo illustrates portajohns have been staked down with rebar at the corners.

Note - There was also debris behind them on the pad.

Inspection Photos

Location Name: Prosper Farms/4-65 2-1-6

Location ID: 443722



**Photo 9.** The photo was taken at the well location facing South. The photo illustrates kochia growing along the interim areas within the location fencing.

Inspection Photos

Location Name: Prosper Farms/4-65 2-1-6

Location ID: 443722



**Photo 10.** The photo was taken at the well location facing South. Refer to the comment for photo 9.

**Photo 11.** The photo was taken at the well location facing Northeast. The photo illustrates loose wires daylighting out of the production pad in the Southwest corner.