

Interim Reclamation and Stormwater Inspection

Date: 8/21/24

Operator: Crestone Peak Resources Operating LLC -
10633

Location ID: 449486

Inspection Document #: 713900900

Arapahoe County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lone Tree/North
Location ID: 449486




Photo 1. The photo was taken at the well location facing East. The photo illustrates location signage at the tank batteries.

Photo 2. The photo was taken at the well location facing Southeast. The photo illustrates the production pad.

Inspection Photos
Location Name: Lone Tree/North
Location ID: 449486



Photo 3. The photo was taken at the well location facing South. The photo illustrates interim areas outside the permanent location fence are dominated by triticale and have been mowed.

Photo 4. The photo was taken at the well location facing West. The photo illustrates the topsoil stockpile is being managed by evidence of mowing however it's dominated by kochia and triticale.

Inspection Photos
Location Name: Lone Tree/North
Location ID: 449486



Photo 5. The photo was taken at the well location facing Southwest. The photo illustrates a representative photo of filterxx wattle across the location and demonstrates that the majority is filled with holes on the top side.

Note - The fence top wire was damage and in need of repair.



Photo 6. The photo was taken at the well location facing Northeast. The photo illustrates the sediment trap in the Southwest corner of the location.

Inspection Photos
Location Name: Lone Tree/North
Location ID: 449486



Photo 7. The photo was taken at the well location facing Southeast. The photo illustrates interim areas North of the location are vegetated with some bare spots.

Photo 8. The photo was taken at the well location facing South. Refer to the comment for photo 7.



Inspection Number: 713900900

Inspection Photos
Location Name: Lone Tree/North
Location ID: 449486



Photo 9. The photo was taken at the well location facing Northeast. The photo illustrates wildlife netting on secondary containment has not been secured correctly creating gaps where wildlife can enter.



Photo 10. The photo was taken at the well location facing Northeast. Refer to the comment for photo 9 .

Inspection Photos
Location Name: Lone Tree/North
Location ID: 449486



Photo 11. The reference photo was taken southwest of the well location facing Southwest.