

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 6540 From entrance to location



Photo # 6541 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 6542 Location



Photo # 6543 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 6544 Location



Photo # 6545 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 6546 Barbed wire fence needs maintenance/wildlife hazard



Photo # 6547 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Aug 26, 2024 at 10:59:07 AM
CO

Photo # 6548 Barbed wire fence needs maintenance/wildlife hazard



Aug 26, 2024 at 10:59:12 AM
CO

Photo # 6549 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 6550 Barbed wire fence needs maintenance/wildlife hazard



Photo # 6551 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH NER 421-18 Pad

Location #: 324406



Photo # 6552 Barbed wire fence needs maintenance/wildlife hazard



Photo # 6553 Barbed wire fence needs maintenance/wildlife hazard