

Shawnee Oil Development Co Inc
USA Shaw 19
Location ID: 313419



Insufficient tank berm



Missing tank labels

Shawnee Oil Development Co Inc
USA Shaw 19
Location ID: 313419



Incomplete signage



Incomplete signage

Shawnee Oil Development Co Inc
USA Shaw 19
Location ID: 313419



Leaking wellhead. No Bradenhead access.



Leaking wellhead. No Bradenhead access.

Shawnee Oil Development Co Inc
USA Shaw 19
Location ID: 313419



Seep area with evidence of incomplete hydrocarbon removal



Soil removal for stained area

Shawnee Oil Development Co Inc
USA Shaw 19
Location ID: 313419



Debris



Debris

Shawnee Oil Development Co Inc
USA Shaw 19
Location ID: 313419



Unmarked anchor



Flagged anchor.

Shawnee Oil Development Co Inc
USA Shaw 19
Location ID: 313419



Location from Northeast corner



Location from Northwest corner

Shawnee Oil Development Co Inc
USA Shaw 19
Location ID: 313419



Location from Southwest corner



Location from Southeast corner