

Inspection Photos


Location: LARAMIE ENERGY LLC CASCADE CREEK/697-08-53

Location ID: 335815

Date: 8/22/2024



Entrance to location - Photo #04997



Location - Photo #05017

Inspection Photos

Location: LARAMIE ENERGY LLC CASCADE CREEK/697-08-53

Location ID: 335815

Date: 8/22/2024



Aug 22, 2024 at 2:16:40 PM
+39.533907,-108.241717 ±4.75m
De Beque



Aug 22, 2024 at 2:21:36 PM
+39.533552,-108.242099 ±4.73m
De Beque

Wellheads - Photo #04998

Wellhead - Photo #05002

Inspection Photos

Location: LARAMIE ENERGY LLC CASCADE CREEK/697-08-53

Location ID: 335815

Date: 8/22/2024



Aug 22, 2024 at 2:23:46 PM
+39.533702,-108.242211 ±4.73m
De Beque

Separators - Photo #05005



Aug 22, 2024 at 2:24:20 PM
+39.533702,-108.242211 ±4.73m
De Beque

Open to wildlife - Photo #05006

Inspection Photos

Location: LARAMIE ENERGY LLC CASCADE CREEK/697-08-53

Location ID: 335815

Date: 8/22/2024



Tank battery - Photo #05015



Pig station - Photo #05023

Inspection Photos

Location: LARAMIE ENERGY LLC CASCADE CREEK/697-08-53

Location ID: 335815

Date: 8/22/2024



PRV's not capped - Photo #05013



Open to wildlife - Photo #05020

Inspection Photos

Location: LARAMIE ENERGY LLC CASCADE CREEK/697-08-53

Location ID: 335815

Date: 8/22/2024



SW corner of location - Photo #05024



SE corner of location - Photo #05025