

Operator: 8 North

Location Name: SHABLE-611N61W 32NENW

Loc ID: 310712

Inspection: 684904657







CA: Stained soil at wellhead. Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence showing that the stained soil has been addressed, and the location is currently in compliance with the 900 and 600 series

CA: Engine; stained soil in engine house, at exhaust. Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence showing that the stained soil has been addressed, and the location is currently in compliance with the 900 and 600 series