

Inspection Photos

ID: 412072

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 8/19/2024

County: Cheyenne



Inspection Photos



Photo 1. Facing southeast toward the EAST SORRENTO COMPRESSOR.



Inspection Photos



Photo 2. Facing southwest toward the tank battery.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID: 412072 | Date: 8/19/2024

Inspection Photos



Photo 3. The sign and labels at the tank battery are faded and missing.



Inspection Photos



Photo 4. There is oil stained soils that has spilled out from the engine skid. The stained soils must be cleaned up and properly disposed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID: 412072 | Date: 8/19/2024

Inspection Photos



Photo 5. There is stained soils around the engine that needs to be cleaned up. The engine on the left appears to be unused and must be removed. The stained soils must be cleaned up and properly disposed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 412072 | Date: 8/19/2024

Inspection Photos



Photo 6. The fuel tank has leaked and has no secondary containment. Stained soils must be cleaned up and properly disposed.



Inspection Photos



Photo 7. There is an electric panel that is outside of the fenced area and must be removed..



Inspection Photos



Photo 8. Facing northwest. The perimeter fence is down and not maintained. This area at the south side of the location has no vegetation and is unused. Unused areas of the location must be reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 412072 | Date: 8/19/2024

Inspection Photos



Photo 9. There is a fuel tank that has rolled off the location and must be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID: 412072 | Date: 8/19/2024