

# Inspection Photos

Loc: 483886

Operator: BNL (ENTERPRISE) INC

Inspection Date: 8/26/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north along the access road.





## Inspection Photos



**Photo 2.** Facing northwest toward the access road. The side of the road needs to be seeded and stabilized





## Inspection Photos



**Photo 3.** Facing west toward the location. The sign has fallen over and the silt fence is down and not maintained.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 8/26/2024



## Inspection Photos



**Photo 4.** The silt fence is down and not maintained.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 8/26/2024



## Inspection Photos



**Photo 5.** Facing toward the soil stock pile. The topsoil has not been seeded and stabilized and weeds are beginning to establish. There is erosion occurring along the topsoil pile and the silt fence is in disrepair.





## Inspection Photos



**Photo 6.** Facing northwest toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 8/26/2024



## Inspection Photos



**Photo 7.** Facing northwest toward the north side of the location. The silt fence is down and not maintained around the entire location.

