

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403903173

Date Received:

08/28/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000869

Inspection Date: 06/18/2024

FIR Submit Date: 06/24/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326188

Location Name: BROWN 32-6-3-N32N6W Number: 3NWSW County: _____

Qtrqtr: NWS Sec: 3 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.044521 Longitude: -107.492236

FACILITY - API Number: 05-067- -00 Facility ID: 326188

Facility Name: BROWN 32-6-3-N32N6W Number: 3NWSW

Qtrqtr: NWS Sec: 3 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.044521 Longitude: -107.492236

CORRECTIVE ACTIONS:

2 CA# 196103

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: _____

Response: CA COMPLETED

Date of Completion: 08/28/2024

Operator
Comment:

Inspection # 714001114 is a clarifying inspection report to confirm the Tribal status of the Brown 32-06-03 1 Location, Location ID 326188. The Southern Ute Indian Tribe owns 80 acre surface parcel; ECMC no longer has jurisdiction or inspection authority on this well and surface location.

ECMC Decision: _____

ECMC
Representative:

3 CA# 196104

Corrective Action: Reclamation needs to be conducted in areas not needed for production operations in accordance with 1003 reclamation rules.

Date: _____

Response: CA COMPLETED

Date of Completion: 08/28/2024

Operator
Comment:

Inspection # 714001114 is a clarifying inspection report to confirm the Tribal status of the Brown 32-06-03 1 Location, Location ID 326188. The Southern Ute Indian Tribe owns 80 acre surface parcel; ECMC no longer has jurisdiction or inspection authority on this well and surface location.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Inspection # 714001114 is a clarifying inspection report to confirm the Tribal status of the Brown 32-06-03 1 Location, Location ID 326188. The Southern Ute Indian Tribe owns 80 acre surface parcel; ECMC no longer has jurisdiction or inspection authority on this well and surface location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 8/28/2024 8:56:47 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403903176	ECMC inspection report documenting change of landownership and jurisdiction
-----------	---

Total Attach: 1 Files