


Operator: CPR

Location Name: Lone Tree North

Loc ID: 449486

Inspection: 713900900







CA: Netting around secondary containment are not installed properly, leaving large holes/gaps allowing wildlife to enter. Comply with Rule 608.

CA Resolution: Operator has appropriately installed wildlife netting to comply with the 600 series.