

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE

Location ID: 334656

Date: 8/28/2024



Location Entrance – Photo #03108



Wellheads – Photo #03109

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE

Location ID: 334656

Date: 8/28/2024



Aug 28, 2024 at 13:25:06
1632 Underwood Ln
Parachute CO 81635
United States

Separators – Photo #03112



Aug 28, 2024 at 13:27:45
1632 Underwood Ln
Parachute CO 81635
United States

Tank Battery – Photo #03114



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE

Location ID: 334656

Date: 8/28/2024



Gas Meter – Photo #03113



Stored Supplies – Photo #03116