

Inspection Photos

August 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326612

Inspection Document #: 714001144

La Plata County, CO

Township: SESW 28 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Montgomery Federal 2
Location ID: 326612



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos

Location Name: Montgomery Federal 2

Location ID: 326612



Photo 2. Gully erosion observed forming in the southern interim reclamation area, stabilization/control measures needed in this area.

Inspection Photos

Location Name: Montgomery Federal 2

Location ID: 326612




Photo 3. View of western cut slope with active erosion, bare soils and sediment deposition occurring. ECB installed in 2020 has degraded, maintenance is needed.

Inspection Photos
Location Name: Montgomery Federal 2
Location ID: 326612



Inspection Photos
Location Name: Montgomery Federal 2
Location ID: 326612



Photo 5. Reference area comprised of Squirrel tail, Pine and Gambel oak.

