

Inspection Photos

August 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326611

Inspection Document #: 714001145

La Plata County, CO

Township: NWNE 33 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Miller Federal 2
Location ID: 326611



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Miller Federal 2
Location ID: 326611



Photo 2. Large patches of Canada and Musk thistle observed in are wilting and area appear to have been treated with herbicide.

Inspection Photos
Location Name: Miller Federal 2
Location ID: 326611



8/23/24

+37.262185,-107.638622

350° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Large patch of field bindweed observed flowering in the northern portion of the disturbance.

API #: 067-08393

Inspection Photos
Location Name: Miller Federal 2
Location ID: 326611



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of southern interim reclamation area where weeds have been treated but minimal desirable vegetation establishment is observed.

API #: 067-08393

Inspection Photos
Location Name: Miller Federal 2
Location ID: 326611



Photo 5. View of active pasture comprised predominantly of smooth brome.

