

Inspection Photos
Location: Silverland 31-22 and Silverland 31-22 TR
Location ID: 334200
API # 05-071-07098, TR 09156



Photo 1 –Well placard on meter house.

Photo 2 – Wellhead and equipment.

Inspection Photos
Location: Silverland 31-22 and Silverland 31-22 TR
Location ID: 334200
API # 05-071-07098, TR 09156



Photo 3 – Tr wellhead and equipment.



Photo 4 – Pit Facility ID 301239, Pit has been backfilled.

Inspection Photos
Location: Silverland 31-22 and Silverland 31-22 TR
Location ID: 334200
API # 05-071-07098, TR 09156



Photo 5 – Area where pit spoil pile was stored.

