

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313134

Inspection Doc: 696206184

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313134



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313134



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313134



Photo 3: Photos examples of Noxious weeds (Knapweed, Scotch thistle) observed established on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313134



Photo 4: Photo taken from the south end of the Location. Photo shows Utility equipment on, and leading to, the Location has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313134



August 21, 2024

Photo 5: Photo taken from the south end of the Location, facing west. Photo shows areas of the Location that have not achieved uniform vegetative cover.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313134



August 21, 2024

Photo 6: Photo taken from north-central areas of the Location, facing north. Photo shows areas of the Location where vegetative establishment is uniform.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313134



August 21, 2024

Photo 7: Photo taken from the west end of the Location, facing south. Photo shows a stockpile/berm remaining on the Location. Location has not been properly contoured, and soils replaced. Soils are barep; BMPs to protect the stockpiled soils from erosion, degradation, weed establishment, as well as BMPs to minimize sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313134



Photo 8: Photos taken from the northwest and northeast ends of the Location, facing north. Photos examples showing the access road to the Location has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

